



Thorney - WWII Condition Assessment

For 15 years CDAS has annually reported on the Thorney Island WWII structures. Initially, the focus was to document sites & record them on the Heritage Environmental Record (HER) database. Now the emphasis is on identifying those sites that are threatened by invasive vegetation and/or coastal erosion. However, new sites are still being identified, often in areas of dense vegetation.



Red dots mark WWII sites

Invasive vegetation

Type 22 Pill Box

2007



2012



Friends of Chichester Harbour, CDAS and other volunteers undertake major clearance of invasive vegetation as well as regular maintenance.

2017



2013



Coastal Erosion

2020



In two seasons the seaward bank has been swept away exposing a wall that is in pristine condition.

2022

